



Preventive Action Report

Printed on:

Wednesday, July 10, 2013

Details			
Raised Date 7/10/2013	Status Open	Owner Petsche, Mike	Number PAR13-274
Target Date 7/14/2013	Standard		Severity
Process	Audit		
Raised By Person Falcon Aviation Ltd	Raised Against (Department or Supplier) Engineering\Drawing		Fault Category
Details			
Falcon Aviation Services is asking DART to incorporate repair procedure supplied to them via email. Originally, Proseal 890 was suggested to FAS but D3562 dwg was revised to replace Magnobond with Scotchweld. Reason: manufacturing complained that the oil or something from Proseal may seeps through powder coat while in the oven. Perhaps the ICA can give the option to use Prosel 890 or Scotchweld at the discretion of the technician.			
Product	D412-630		
Document	Root Cause		
Closed By	Closed Date	Resolution	

Corrective Action			
Target Date 7/13/2013	Owner	Closed Date	Closed By
Details			

Actions			
Number	Owner	Target Date	Completed Date
Details		Response	
1	Siemens, Harvey	8/9/2013	
Revise ICA-D412-630 accordingly.			
2	Siemens, Harvey	8/16/2013	
Release ICA-D412-630 on ECN.			
3	Bellavance, Marc	8/16/2013	
Provide revised copy of ICA-D412-630 to FAS.			

Verification & Review			
Target Date 7/14/2013	Owner	Closed Date	Closed By
Details			

Actions			
Number	Owner	Target Date	Completed Date
Details		Response	